



### **Table of Contents**

1.	Introduction1		
2.	Wall Beach Water System12.1Groundwater Wells2.2Reservoirs2.3Distribution System		
3.	Water Sampling and Testing Program		
4.	Water Quality - Source Water and Distribution System		
5.	Water Quality Inquiries and Complaints2		
6.	Groundwater Production and Consumption2		
7.	Maintenance Program		
8.	Water System Projects38.12007 Completed Studies & Projects38.22008 Proposed Projects & Upgrades48.32008 Proposed Studies4		
9.	Emergency Response Plan		
10.	Cross Connection Control		
11.	Closing4		

Appendix A - Map of Wall Beach Water Local Service Area

Appendix B - Water Quality Testing Results

Appendix C - Emergency Response Plan



### 1. Introduction

The following annual report describes the Wall Beach Water Local Service Area and summarizes the water quality and production data from 2007. This report also includes a summary of inquiries and complaints, completed and proposed maintenance activities, the Emergency Response Plan, and the Cross Connection Control Program.

This report is to be submitted to the Vancouver Island Health Authority by the Spring of 2008.

### 2. Wall Beach Water System

The Wall Beach Water Service Area was established in 1992 and comprises a small area lying west of Seahaven Road on the Nanoose Peninsula. During the winter months the water source for Wall Beach comes from the Madrona #4 well located nearby, which is not chlorinated. The water supply is supplemented, when required, with chlorinated water from the Fairwinds water system. From May to October each year, the water source to Wall Beach is replaced by surface water from the Englishman River, which has been chlorinated. Both the groundwater and surface water sources are stored in the nearby Madrona reservoir. A map of the Wall Beach Water System is provided in Appendix A for reference.

#### 2.1 Groundwater Wells

There are no groundwater production wells in the Wall Beach Water System. Drinking water is supplied from the adjacent Madrona Water System.

#### 2.2 <u>Reservoirs</u>

No reservoirs are present in the Wall Beach Water System. Drinking water is stored in the nearby Madrona reservoir.

#### 2.3 Distribution System

The water distribution system in Wall Beach is comprised of 100mm and 150mm asbestosconcrete watermains, and 150mm PVC watermains. Fire hydrants are located throughout the system.

#### 3. Water Sampling and Testing Program

Water sampling and testing is carried out weekly in the adjacent Madrona water distribution system, which is considered to be representative of the drinking water in the Wall Beach water system. The following table includes a summary of all testing in the Madrona water system:

Timing	Location	Tests
Weekly	RDN (in-house) Laboratory	Total coliforms, E.Coli, Temperature, pH, Conductivity, Chlorine residual, Salinity Total Dissolved Solids, Iron, Manganese
Weekly (Health Dept. Requirement)	North Island Labs	Total, Fecal coliforms
Annual Source Water Testing	North Island Labs	Complete potability testing of each well
Annual System Water Testing	North Island Labs	Complete potability testing of distribution system





### 4. Water Quality - Source Water and Distribution System


Up-to-date water quality reports and lab data are posted monthly on the RDN website at <u>www.rdn.bc.ca</u> in the WaterSmart section, under "Communities". Tables of water quality testing results for both the source water and distribution system are provided at the end of this report under Appendix B.

### 5. Water Quality Inquiries and Complaints

No complaints or inquiries were received from the Wall Beach water service area.

#### 6. Groundwater Production and Consumption


The 2007 monthly groundwater production for Wall Beach/Madrona is shown in the chart below. The number of Wall Beach water service connections represents only 14 of 317 total water connections in the Wall Beach/Madrona area. Groundwater production has been charted against rainfall data from the City of Parksville website to show how rainfall affects the amount of groundwater pumped.







The monthly groundwater production for the Wall Beach/Madrona area for the past 7 years is shown in the chart below. Groundwater production in 2007 was typically lower than previous years.



### **Consumption**

In the Fall/Winter of 2007, the average usage per home in the Wall Beach/Madrona area was 0.52 cubic metres per day (114 imperial gallons). In the summer, the average water usage was 1.2 cubic metres per day (262 imperial gallons).

### 7. Maintenance Program

Watermains are flushed once annually; in the Spring.

### 8. Water System Projects

#### 8.1 2007 Completed Studies & Projects

- A Drinking Water Watershed Protection Action Plan was completed.
- An Innovative Water Use and Re-Use Study was completed.
- A Water Use Bylaw Best Practices Review was completed.
- A Nanoose Bay Peninsula Water Sourcing Study was completed.
- A formalized Cross Connection Control Program was initiated.
- A comprehensive water conservation program (WaterSmart) was carried out from May to October.
- The RDN WaterSmart website was updated and improved.
- The Emergency Response Plan was reviewed and updated.
- A SCADA (Supervisory Control and Data Acquisition) Study was initiated.
- A pilot treatment plant for iron & manganese removal from drinking water was setup and run for a two-week trial.
- The annual watermain flushing was completed.





### 8.2 2008 Proposed Projects & Upgrades

- Radio Meter Pilot Study (for water meters)
- Well exploration program
- Upgrades to flush-outs
- New signage for all Utilities facilities
- Re-keying all locked facilities
- Implement innovative use and re-use technology
- Stand-alone water testing stations to be installed
- Promote Cross Connection Control awareness and facility audits

### 8.3 2008 Proposed Studies

- Complete SCADA study and integrate into 2009 budget
- Rainwater management strategy
- Sodium hypochlorite vs. on-site chlorine generation
- Comprehensive capital plan development

### 9. Emergency Response Plan

The Emergency Response Plan (ERP) was reviewed and updated in 2007. A copy of the ERP is attached in Appendix C.

### **10.** Cross Connection Control

A formalized Cross Connection Control Program was initiated in 2007. Cross connection controls in-place include dual check valves at each service connection, fire hydrant use permits, and water supply bylaws noting discontinued service if a threat to the water supply is perceived by staff.

A consultant who specializes in municipal Cross Connection Control was hired to enhance the RDN Cross Connection Control Program in 2007/2008. The program in 2008 will include:

- A review and comparison of successful cross-connection control programs implemented by other small water systems nearby,
- A survey of existing or potential cross-connection risks for each category of RDN customer (i.e., residential, commercial, industrial, institutional, etc.),
- An audit of RDN-owned facilities in each water service area,
- The preparation of a draft bylaw to allow enforcement of the Cross Connection Control Program,
- The set up of a customer database with a maintenance history of testable backflow prevention assemblies at each facility, and
- Staff training and certification in Backflow Assembly Testing (BCWWA certified).

### 11. Closing

An annual report for the year 2008 will be prepared and submitted to the Vancouver Island Health Authority in the Spring of 2009. Annual reports are also available on our website at <u>www.rdn.bc.ca</u> in the WaterSmart section, under "Communities".





## APPENIDX A


# MAP OF WALL BEACH

### WATER LOCAL SERVICE AREA



# WALL BEACH

# WATER LOCAL SERVICE AREA







## **APPENDIX B**

# WATER QUALITY TESTING RESULTS





## **APPENDIX C**

## **EMERGENCY RESPONSE PLAN**

